


Roof and External Walls	
1	Roof Sheets and Tiles
2	Guttering and Drainpipe
3	Wall Cladding
4	Soffit Boards
5	Panel Beneath Window
6	Roofing felt and Coating to Metal Wall Cladding
Boiler, Vessels and Pipework	
7	Lagging on Boiler, pipework, calorifier etc
8	Damaged Lagging and associated Debris
9	Paper Lining under non-asbestos pipe lagging
10	Gasket in pipe and vessel joints
11	Rope seal on boiler access hatch and between cast iron boiler sections
12	Paper lining inside steel boiler casing
13	Boiler Flue
Ceilings	
14	Spray coating to ceilings, walls, beams/columns
15	Loose asbestos in ceiling/floor cavity
16	Tiles, slats, canopies and firebreaks above ceilings
17	Texture coatings and paints
Interior walls and panels	
18	Loose asbestos inside partition walls
19	Partition walls
20	Panel beneath window
21	Panel lining to lift shaft
22	Paneling to vertical and horizontal beams
23	Panel behind electrical equipment
24	Panel on access hatch to service riser
25	Panel Lining service riser and floor
26	Heater cupboard around domestic boiler
27	Panel behind/under heater
28	Panel on, or inside, fire door
29	Bath panel
Flooring materials	
30	Floor tiles, Linoleum and paper backing, lining to suspended floor
Air handling systems	
31	Lagging
32	Gaskets
33	Anti-vibration gaiter
Domestic Appliances	
34	Gaskets, rope seals and panels in domestic boilers
35	'Caposil' insulating blocks, panels, paper, string etc in domestic heater
36	String seals on radiators
Other	
37	Fire blanket
38	Water tank
39	Brake/clutch linings



**This diagram only shows typical locations for materials containing asbestos a full and detailed survey is required to identify all asbestos containing materials*